

Fan Connection User Manual

3 pin 12V DC




- (yellow) RPM Signal / Tachometric Signal (From Fan)
- (red) 12V DC (+)
- (black) Ground (-)

3 pin to 4 pin Molex Adapter




4 pin 12V DC fan




- (blue) RPM Signal (From Motherboard)
- (yellow) RPM Signal / Tachometric Signal (From Fan)
- (red) 12V DC (+)
- (black) Ground (-)

Connection: Connect the 3-pin connector to motherboard fan header, OR connect the Molex connector to PSU.


3-pin connector to motherboard Fan



Molex connector to PSU if using the 3-pin to 4-pin molex adapter



4-pin connector to motherboard Fan



853704001299	b-PWM80 Translucent Black
853704001282	b-PWM80 Translucent Blue
853704001305	b-PWM80 Translucent Red
853704001329	b-PWM90 Translucent Black
853704001312	b-PWM90 Translucent Blue
853704001435	b-PWM90 Translucent Red
853704001220	b-PWM120 Translucent Black
853704001213	b-PWM120 Translucent Blue
853704001237	b-PWM120 Translucent Red
853704001244	b-PWM140 Translucent Black
853704001251	b-PWM140 Translucent Blue
853704001268	b-PWM140 Translucent Red

Designed by Bluegears in USA
www.bluegears.com